



Hunter Fan Recalls Lighting Products Due to Shock Hazard



Name of Product:

Hunter branded Devon Park, Astwood, Highland Hill, Kerrison and Van Nuys light fixtures.

Hazard:

The internal wires in the lights can be damaged, posing an electric shock hazard to the consumer.

Remedy:

Refund

Recall Date:

November 10, 2022

Units:

About 2,600

Recalled Hunter Fan 19143 Devon Park 1 Light Wall Sconce in Onyx Bengal



Consumer Contact

Hunter toll-free at 866-326-2003 from 8 a.m. to 3 p.m. CT Monday through Friday or online at www.hunterfan.com and click on the "Recall" link at the bottom of the page or www.hunterfan.com/recall for more information.

Recall Details

Description:

This recall involves 41 models of Hunter lighting fixtures from the Devon Park, Astwood, Highland Hill, Kerrison, and Van Nuys lighting collections. The model number can be found on a label behind the light when removed from the wall. The lights were sold with single, 2, 3, 4 and 5-light fixtures and in various finishes including brushed and polished nickel, Onyx black, Alturas gold, Distressed white and rust. Lights included in the recall are listed below. To view photos of all recalled models, visit www.hunterfan.com/recall.

Light Collection	Description	Model	
Devon Park	Sconce	19143	
		19144	
	2 Light Vanity	19145	
		19146	
	3 Light Vanity	19147	
		19148	
	4 Light Vanity	19149	
		19150	
	Astwood	2 Light Vanity	19127
			19128
		19963	
		19964	
3 Light Vanity		19129	
		19130	
		19965	
		19966	
4 Light Vanity		19131	
		19132	
	19967		
	19968		
5 Light Linear		19121	
		19122	
		19955	
		19956	
Highland Hill	Chandelier	19287	
		19288	

		19982
Kerrison	2 Light Vanity	19550
		19551
	3 Light Vanity	19552
		19553
	4 Light Vanity	19554
		19555
Van Nuys	2 Light Vanity	19301
		19302
	3 Light Vanity	19303
		19304
	4 Light Vanity	19305
		19306
	4 Light Linear	19323
		19324

Remedy:

Consumers should immediately stop using the recalled lighting products and contact Hunter to receive a full refund.

Incidents/Injuries:

Hunter has received seven reports of the lights causing the circuit breaker to trip. No injuries have been reported.

Sold At:

Online at www.hunterfan.com and other online lighting websites from October 2021 through September 2022 for between \$110 and \$450.

Importer(s):

Hunter Fan Company, of Memphis, Tennessee

Manufactured In:

China

Recall number:

23-041

